# Vehicle Detail Report

## Toyota Corolla 2017 Change the double engine 1.8L E-CVT Elite Edition China V

## Basic Information

| | |
|---|---|
| Brand | **Toyota** |
| Mileage | **98,000 km** |
| Color | **White** |
| First Registration | **2018-10-01** |
| Transfer Count | **0** |

## Vehicle Images
















## Vehicle Condition

1. Left roof side member, Left upper side rail, Paint repair, Body panel repair. 2. Right roof side member, Right upper side rail, Paint repair. 3. Left bottom side member, Left rocker panel, Paint repair, Outer-side body panel repair. 4. Right bottom edge beam, Right rocker panel, Paint repair, Outer-side deformation, Outer-side body panel repair. 5. Left, B, Column Sealing, Inner side of left B-pillar, Non-accident-related deformation. 6. Left, C, Column Sealing, Inner side of left C-pillar, Deformation. 7. Right, B, Column Sealing, Inner side of right B-pillar, Non-accident-related deformation. 8. Right, C, Column Sealing, Inner side of right C-pillar, Deformation. 9. Rear body panel, Deformation, Body panel repair. 10. Trunk floor, Spare wheel well, Deformation, Water stains. 11. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 12. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 13. Left rear quarter panel, Paint repair, Body panel repair. 14. Right rear quarter panel, Paint repair, Body panel repair. 15. Body floor pan, Aftermarket underbody coating.

---

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.