


Vehicle Detail Report

Changan CS85 COUPE 2019 2.0T Moving version Country VI

Basic Information

Brand	Changan
Mileage	59,000 km
Color	White
First Registration	2019-10-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rocker panel, Scratch damage. 2. Right rocker panel, Scratch damage. 3. Right front fender structure, Deformation. 4. Driver's seat rails and frame, Signs of removal. 5. Front passenger seat rails and frame, Signs of removal. 6. Left rear quarter panel, Paint repair. 7. Right rear quarter panel, Paint repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.