Vehicle Detail Report

Jetour Freedom 2025 1.5TD Discover

Basic Information

Brand	**Jetour**
Mileage	**16,000 km**
Color	**Silver-gray**
First Registration	**2025-04-01**
Transfer Count	**0**



Vehicle Images
















1914









P R N D
0
138


正在倒车，请注意车辆周边安全







Vehicle Condition

1. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 2. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 3. Left front door, Paint chip, Scratch. 4. Left rear door, Paint chip, Deformation. 5. Right rear door, Scratch. 6. Left front fender, Scratch. 7. Right front fender, Deformation, Scratch damage. 8. Windshield, Stone chip.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.