Vehicle Detail Report

Jetour X70L 2026 2.0TD 8AT Flagship

Basic Information

Brand	**Jetour**
Mileage	**20,000 km**
Color	**Green**
First Registration	**2025-10-01**
Transfer Count	**0**



Vehicle Images


























Vehicle Condition

1. Right roof side member, Right upper side rail, Scratch. 2. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 3. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 4. Hood, Hood, Paint chip. 5. Front bumper, Scratch damage. 6. Right front door, Scratch. 7. Right rear door, Paint chip, Scratch. 8. Trunk lid, Trunk lid, Scratch. 9. Left front fender, Scratch. 10. Left rear quarter panel, Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.