Vehicle Detail Report

Honda Civic 2020 HATCHBACK 220TURBO CVT Tide Cool Control


Basic Information


Brand	**Honda**
Mileage	**60,000 km**
Color	**White**
First Registration	**2022-06-01**
Transfer Count	**0**

Vehicle Images


















Vehicle Condition

1. Right, B, Column Sealing, Inner side of right B-pillar, Non-accident-related deformation. 2. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 3. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 4. Right rear quarter panel, Paint repair, Body panel repair. 5. Airbag, Signs of removal.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.