Vehicle Detail Report

Jetour T2 2025 2.0TD XWD Expedition+

Basic Information


Brand	**Jetour**
Mileage	**16,000 km**
Color	**Black**
First Registration	**2025-06-01**
Transfer Count	**0**

Vehicle Images












Vehicle Condition

1. Right roof side rail: Right upper side rail, Scratch (Not accident-related). 2. Left B-pillar edge: Inner side of left B-pillar, Scratch (Not accident-related). 3. Left C-pillar edge: Inner side of left C-pillar, Scratch (Not accident-related). 4. Trunk floor panel: Spare wheel well (Trunk floor panel), Soiling (Not accident-related). 5. Driver's seat slide rails: Driver's seat rails and frame, Signs of removal (Not flood-related). 6. Front passenger seat slide rails: Front passenger seat rails and frame, Signs of removal (Not flood-related). 7. Left rear quarter panel: Paint chip.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.