Vehicle Detail Report

Honda Accord 2023 Sharp ·T move 260TURBO Smart Edition


Basic Information

Brand	**Honda**
Mileage	**46,000 km**
Color	**Black**
First Registration	**2023-09-01**
Transfer Count	**0**

Vehicle Images












Vehicle Condition

1. Right bottom edge beam, Right rocker panel, Scratch damage. 2. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 3. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 4. Left rear quarter panel, Scrape, Deformation. 5. Right rear quarter panel, Deformation. 6. Body floor pan, Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.