Vehicle Detail Report

Honda Civic 2020 HATCHBACK 220TURBO CVT Tide Cool Control

Basic Information


Brand	**Honda**
Mileage	**35,000 km**
Color	**Black**
First Registration	**2022-08-01**
Transfer Count	**0**

Vehicle Images









Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Deformation, Non-accident-related deformation. 2. Left, C, Column Sealing, Inner side of left C-pillar, Deformation. 3. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 4. Passenger seat track, Front passenger seat rails and frame, Signs of removal.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.