Vehicle Detail Report


Honda Civic 2020 HATCHBACK 220TURBO CVT Tide Cool Control

Basic Information

Brand	**Honda**
Mileage	**78,000 km**
Color	**Red**
First Registration	**2020-08-01**
Transfer Count	**0**

Vehicle Images









Vehicle Condition

1. Radiator support, Signs of removal. 2. Left, A, Column Sealing, Inner side of left A-pillar, Deformation. 3. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 4. Right rear quarter panel, Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.