Vehicle Detail Report

Geely Auto Borui ePro 2018 1.5T Yaoxiang edition


Basic Information


Brand	**Geely**
Mileage	**79,000 km**
Color	**Blue**
First Registration	**2018-08-01**
Transfer Count	**0**

Vehicle Images














Vehicle Condition

1. Radiator support: Signs of removal, Replaced. 2. Left front frame rail: Deformation. 3. Right front frame rail: Deformation. 4. Left rear quarter panel: Paint chip, Scrape, Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.