Vehicle Detail Report

Honda LIFE 2020 1.5L CVT SPO-SS Smart edition

Basic Information

Brand	**Honda**
Mileage	**59,000 km**
Color	**Red**
First Registration	**2022-01-01**
Transfer Count	**0**

Vehicle Images

























LIFE
SPORT







Vehicle Condition

1. Radiator support: Signs of removal. 2. Right bottom edge beam: Right rocker panel, Inner-side deformation. 3. Right A-pillar edge: Inner side of right A-pillar, Deformation. 4. Left front fender liner: Left front fender structure, Deformation. 5. Right rear quarter panel: Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.