Vehicle Detail Report

Geely Preface 2020 2.0T Flagship

Basic Information


Brand	**Geely**
Mileage	**99,000 km**
Color	**Blue**
First Registration	**2020-11-01**
Transfer Count	**0**


Vehicle Images
























Vehicle Condition

1. Radiator support, Signs of removal, Replaced. 2. Left rear frame rail, Deformation. 3. Left front fender lining, Left front fender structure, Deformation, Body panel repair. 4. Rear body panel, Deformation. 5. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 6. Left rear quarter panel, Paint repair, Body panel repair. 7. Right rear quarter panel, Paint repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.