Vehicle Detail Report

Honda Elysion 2022 2.0L Hybrid Deluxe Edition

Basic Information

Brand	**Honda**
Mileage	**140,000 km**
Color	**Black**
First Registration	**2022-06-01**
Transfer Count	**1**

Vehicle Images




















Vehicle Condition

1. Left roof side member, Left upper side rail, Scratch. 2. Left bottom side member, Left rocker panel, Scratch damage. 3. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 4. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 5. Front bumper, Paint repair. 6. Left rear door, Scratch. 7. Left rear wheel rim, Scrape. 8. Right rear wheel rim, Scrape. 9. Left front fender, Paint chip, Scratch damage, Deformation, Signs of removal, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.