Vehicle Detail Report

Hyundai Encino 2019 1.6T Iron Man Edition

Basic Information


Brand	**Hyundai**
Mileage	**39,000 km**
Color	**Silver-gray**
First Registration	**2021-06-01**
Transfer Count	**0**

Vehicle Images














Vehicle Condition

1. Right bottom edge beam, Right rocker panel, Scratch damage, Inner-side deformation. 2. Trunk floor, Spare wheel well, Mold stains, Water stains. 3. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 4. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 5. Body floor pan, Aftermarket underbody coating.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.