Vehicle Detail Report

Toyota Levin 2023 Dual Power 1.8L Luxury Edition




Basic Information

Brand	**Toyota**
Mileage	**70,000 km**
Color	**White**
First Registration	**2023-09-01**
Transfer Count	**1**


Vehicle Images











Vehicle Condition

1. Firewall, Deformation. 2. Right roof side member, Right upper side rail, Deformation. 3. Right bottom edge beam, Right rocker panel, Outer-side deformation. 4. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 5. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 6. Right rear quarter panel, Deformation. 7. Body floor pan, Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.