Vehicle Detail Report

Honda CR-V 2020 Shining Edition 240TURBO CVT 2WD Comfort Version


Basic Information



Brand	**Honda**
Mileage	**61,000 km**
Color	**Black**
First Registration	**2020-01-01**
Transfer Count	**0**


Vehicle Images











Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Dent. 2. Hood, Hood, Scratch. 3. Front bumper, Scrape, Scratch damage. 4. Rear bumper, Scrape, Scratch damage. 5. Left front door, Paint chip, Scratch. 6. Right front door, Paint chip, Deformation, Scratch, Scratch damage. 7. Left rear door, Paint chip, Scratch. 8. Right rear door, Paint chip, Scratch. 9. Trunk lid, Trunk lid, Scratch. 10. Left front fender, Paint chip, Deformation, Scratch. 11. Right front fender, Scratch, Scratch damage. 12. Left rear quarter panel, Scratch. 13. Right rear quarter panel, Paint chip, Scratch, Scrape. 14. Windshield, Stone chip. 15. Left headlight, Aging, Scratch. 16. Left tail light, Scratch. 17. Body floor pan, Aftermarket underbody coating.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.