# Vehicle Detail Report

## Kia Run 2015 1.6L Automatic Special


## Basic Information

| | |
|---|---|
| Brand | **Kia** |
| Mileage | **100,000 km** |
| Color | **White** |
| First Registration | **2016-03-01** |
| Transfer Count | **0** |


## Vehicle Images
















## Vehicle Condition

1. Left roof side rail: Left upper side rail, Paint repair, Body panel repair. 2. Right B-pillar edge: Inner side of right B-pillar, Non-accident-related deformation. 3. Driver's seat slide rails: Driver's seat rails and frame, Corrosion. 4. Left rear quarter panel: Paint repair. 5. Right rear quarter panel: Paint repair, Body panel repair.

---

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.