Vehicle Detail Report

Hyundai Lafesta 2021 280TGDi DCT Luxury Sport Dynamic Enjoyment edition

Basic Information

Brand	**Hyundai**
Mileage	**39,000 km**
Color	**Dark gray**
First Registration	**2022-01-01**
Transfer Count	**0**

Vehicle Images

























Vehicle Condition

1. Left B-pillar edge: Inner side of left B-pillar, Scratch. 2. Trunk floor panel: Spare wheel well (Trunk floor panel), Water stains. 3. Driver's seat slide rails: Driver's seat rails and frame, Signs of removal. 4. Front passenger seat slide rails: Front passenger seat rails and frame, Signs of removal. 5. Right rear quarter panel: Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.