Vehicle Detail Report

Honda Avancier 2020 240 TURBO CVT Smart Edition

Basic Information



Brand	**Honda**
Mileage	**58,000 km**
Color	**Black**
First Registration	**2021-01-01**
Transfer Count	**0**

Vehicle Images









Vehicle Condition

1. Headliner, Soiling. 2. Hood, Hood, Deformation. 3. Front bumper, Paint repair, Scrape, Scratch damage, Damage, Signs of removal. 4. Rear bumper, Deformation, Scrape, Scratch damage. 5. Left front door, Paint chip, Scrape, Deformation, Paint repair. 6. Right front door, Paint chip, Paint repair, Scrape, Scratch, Scratch damage. 7. Left rear door, Paint chip, Scrape, Scratch. 8. Right rear door, Paint chip, Paint repair, Deformation, Scrape, Scratch. 9. Trunk lid, Trunk lid, Scratch. 10. Left front fender, Scrape, Scratch. 11. Right front fender, Paint chip, Deformation, Scrape, Scratch. 12. Left rear quarter panel, Scratch, Scrape. 13. Right rear quarter panel, Scrape, Deformation. 14. Windshield, Scratch. 15. Left front door glass, Scratch. 16. Right front door glass, Scratch. 17. Left rear door glass, Scratch. 18. Right rear door glass, Scratch. 19. Left tail light, Scratch. 20. Right tail light, Scratch. 21. Headliner, Soiling.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.