Vehicle Detail Report

Changan CS85 COUPE 2019 1.5T Moving version


Basic Information


Brand	**Changan**
Mileage	**59,000 km**
Color	**White**
First Registration	**2020-01-01**
Transfer Count	**0**

Vehicle Images
























Vehicle Condition

1. Right bottom edge beam, Right rocker panel, Outer-side deformation. 2. Headliner, Soiling. 3. Left rear quarter panel, Paint chip, Scratch. 4. Right rear quarter panel, Paint chip, Deformation. 5. Headliner, Soiling.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.