


Vehicle Detail Report

Toyota Sienna 2021 2.5L Hybrid Comfort Edition

Basic Information

Brand	Toyota
Mileage	100,000 km
Color	Blue
First Registration	2022-11-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left bottom side member, Left rocker panel, Inner-side deformation. 2. Right bottom edge beam, Right rocker panel, Inner-side deformation. 3. Left, B, Column Sealing, Inner side of left B-pillar, Scratch, Dent, Non-accident-related deformation. 4. Driver's seat, Driver's seat, Damage.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.