


# Vehicle Detail Report

Hyundai ix25 2015 1.6L Automatic two-drive intelligent type GLS

## Basic Information

Brand	Hyundai
Mileage	80,000 km
Color	Orange
First Registration	2016-01-01
Transfer Count	0

## Vehicle Images





## Vehicle Condition

1. Heavy wear. 2. Valve cover gasket, Signs of removal. 3. Hood, Body panel repair. 4. Left front door, Replaced. 5. Left rear door, Body panel repair. 6. Right rear door, Paint repair. 7. Left front fender, Paint repair. 8. Right front fender, Body panel repair. 9. Left rear quarter panel, Body panel repair. 10. Left rocker panel exterior trim, Scratch damage. 11. Right rocker panel exterior trim, Scratch damage. 12. Mold stains.

---

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.