

Vehicle Detail Report

Mercedes-Benz CLS 2012 AMG CLS 63

Basic Information

Brand	Mercedes-Benz
Mileage	130,000 km
Color	Black
First Registration	2013-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Radiator support, Signs of removal. 2. Left upper side rail, Paint repair. 3. Inner side of left B-pillar, Scratch. 4. Inner side of right C-pillar, Scratch. 5. Spare wheel well, Dust and sand residue, Water stains. 6. Left rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.