


Vehicle Detail Report

Jetour X70 PLUS 2022 1.6T DCT ground Pro 5 seat

Basic Information

Brand	Jetour
Mileage	32,000 km
Color	White
First Registration	2023-04-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Inner side of left B-pillar, Scratch, Non-accident-related deformation. 2. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.