Vehicle Detail Report

Jetour X70 PLUS 2025 1.5T 7DCT Flagship Edition 7 seat

Basic Information

Brand	**Jetour**
Mileage	**7,000 km**
Color	**White**
First Registration	**2024-09-01**
Transfer Count	**0**

Vehicle Images























JETOUR

Normal
0
0.8






Vehicle Condition

1. Hood, Hood, Scratch. 2. Front bumper, Scratch damage. 3. Rear bumper, Scratch damage. 4. Left front door, Paint chip, Scratch. 5. Right front door, Paint chip, Deformation, Scratch. 6. Left rear door, Paint chip, Scratch. 7. Right rear door, Paint chip, Deformation, Scratch. 8. Trunk lid, Trunk lid, Scratch. 9. Left front fender, Scratch. 10. Right front fender, Scratch, Scratch damage. 11. Left rear quarter panel, Scratch. 12. Right rear quarter panel, Scratch. 13. Right headlight, Scratch. 14. Left tail light, Scratch. 15. Right tail light, Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.