Vehicle Detail Report

Honda Accord 2023 Sharp ·T move 260TURBO Premium Edition

Basic Information

Brand	**Honda**
Mileage	**37,000 km**
Color	**White**
First Registration	**2023-11-01**
Transfer Count	**0**

Vehicle Images
























Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Scratch, Dent. 2. Driver’s seat slide rail, Driver's seat rails and frame, Signs of removal. 3. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 4. Right rear quarter panel, Scratch damage.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.