

Vehicle Detail Report


Exeed VX 2023 2.0T Four-Wheel Drive Star
Glory Seven seats


Basic Information

Brand	Exeed
Mileage	46,800 km
Color	Black
First Registration	2024-01-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Inner side of left B-pillar, Scratch, Non-accident-related deformation. 2. Inner side of right C-pillar, Paint repair. 3. Spare wheel well, Dust and sand residue. 4. Driver's seat rails and frame, Signs of removal. 5. Front passenger seat rails and frame, Signs of removal. 6. Headliner, Soiling. 7. Left rear quarter panel, Scratch, Deformation. 8. Right rear quarter panel, Scrape. 9. Headliner, Soiling.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.