Vehicle Detail Report

Toyota Corolla 2017 Restyling 1.6L S-CVT GL China V



Basic Information

Brand	**Toyota**
Mileage	**70,000 km**
Color	**White**
First Registration	**2018-06-01**
Transfer Count	**0**

Vehicle Images








Vehicle Condition

1. Right bottom edge beam, Right rocker panel, Paint repair, Outer-side body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.