Vehicle Detail Report

Hyundai ix35 2015 2.0L Automatic Two-wheel drive Intelligent type China V




Basic Information


Brand	**Hyundai**
Mileage	**148,000 km**
Color	**Champagne color**
First Registration	**2015-12-01**
Transfer Count	**0**

Vehicle Images











Vehicle Condition

1. Left B-pillar edge: Deformation. 2. Trunk floor panel: Corrosion. 3. Left rear quarter panel: Deformation. 4. Left rear quarter panel: Scrape. 5. Right rear quarter panel: Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.