


Vehicle Detail Report

Volkswagen Passat 2021 330TSI Elite Edition

Basic Information

Brand	Volkswagen
Mileage	20,000 km
Color	Black
First Registration	2021-08-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right rocker panel, Scratch damage. 2. Inner side of right C-pillar, Body panel repair. 3. Left rear quarter panel, Paint repair, Body panel repair. 4. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.