

# Vehicle Detail Report

## Volkswagen Sagitar 2021 200TSI DSG Premium Edition

### Basic Information

Brand	Volkswagen
Mileage	18,000 km
Color	White
First Registration	2021-11-01
Transfer Count	1

### Vehicle Images







## Vehicle Condition

1. Right rocker panel, Outer-side deformation. 2. Inner side of left C-pillar, Scratch. 3. Driver's seat rails and frame, Signs of removal. 4. Front passenger seat rails and frame, Signs of removal. 5. Hood, Deformation. 6. Front bumper, Paint repair, Damage. 7. Rear bumper, Paint chip. 8. Left front door, Paint chip, Deformation. 9. Right front door, Deformation. 10. Left rear door, Deformation. 11. Left front fender, Scratch damage. 12. Right rear quarter panel, Deformation. 13. Right tail light, Scratch.

---

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.