

Vehicle Detail Report


Jetour X70 PLUS 2025 1.5T 6DCT The perfect edition 7 seat



Basic Information

Brand	Jetour
Mileage	27,000 km
Color	Black
First Registration	2024-12-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Left bottom side member, Left rocker panel, Scratch damage. 2. Right bottom edge beam, Right rocker panel, Scratch damage. 3. Left, B, Column Sealing, Inner side of left B-pillar, Scratch. 4. Interior wiring harness, Left sill wiring harness, Dust and sand residue.

"●" = Standard equipment

"_ " = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.