

Vehicle Detail Report

Hyundai Tucson 2021 Tucson L 1.5T GLX Two-wheel drive elite version

Basic Information

Brand	Hyundai
Mileage	49,000 km
Color	Black
First Registration	2022-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Right bottom edge beam, Right rocker panel, Inner-side deformation. 2. Left, B, Column Sealing, Inner side of left B-pillar, Dent. 3. Left, C, Column Sealing, Inner side of left C-pillar, Scratch. 4. Right, B, Column Sealing, Inner side of right B-pillar, Scratch. 5. Body floor pan, Aftermarket underbody coating.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.