Vehicle Detail Report

Geely Preface 2020 2.0T Flagship

Basic Information


Brand	**Geely**
Mileage	**80,000 km**
Color	**Blue**
First Registration	**2020-11-01**
Transfer Count	**0**


Vehicle Images














Vehicle Condition

1. Right front fender lining, Right front fender structure, Deformation. 2. Left rear quarter panel, Paint repair, Body panel repair. 3. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.