

Vehicle Detail Report

BMW 5 Series 2022 Second change 525Li M Sports suit

Basic Information

Brand	BMW
Mileage	19,900 km
Color	Black
First Registration	2023-04-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rear quarter panel, Paint repair, Body panel repair. 2. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.