


Vehicle Detail Report

Geely Okavango 2022 1.8TD DCT Flagship

Basic Information

Brand	Geely
Mileage	82,000 km
Color	Dark gray
First Registration	2022-06-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left bottom side member, Left rocker panel, Inner-side deformation. 2. Rear body panel, Deformation. 3. Driver's seat slide rail, Driver's seat rails and frame, Corrosion. 4. Passenger seat track, Front passenger seat rails and frame, Corrosion. 5. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.