Vehicle Detail Report

Chery Arrizo 8 2022 1.6TGDI DCT Elegance


Basic Information

Brand	**Chery**
Mileage	**8,000 km**
Color	**Champagne color**
First Registration	**2022-12-01**
Transfer Count	**0**

Vehicle Images
















Vehicle Condition

1. Right, B, Column Sealing, Deformation. 2. Left rear quarter panel, Scrape.
3. Right rear quarter panel, Paint repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.