

Vehicle Detail Report

Volkswagen Tavendor 2023 380TSI Four-wheel drive R-Line Tour Edition

Basic Information

Brand	Volkswagen
Mileage	68,000 km
Color	Black
First Registration	2023-08-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Corrosion. 2. Right rear door, Body panel repair. 3. Left front fender, Paint repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.