

Vehicle Detail Report

Hyundai Tucson 2020 280TGD Dual-clutch two-drive smart joint version Country VI

Basic Information

Brand	Hyundai
Mileage	72,000 km
Color	White
First Registration	2020-07-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Right, B, Column Sealing, Inner side of right B-pillar, Non-accident-related deformation. 2. Right, C, Column Sealing, Inner side of right C-pillar, Deformation, Non-accident-related deformation. 3. Headliner, Soiling. 4. Left rear quarter panel, Scratch. 5. Headliner, Soiling.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.