

Vehicle Detail Report



Jetour X90 C-DM 2025 1.5TD DHT Luxury Edition

Basic Information

Brand	Jetour
Mileage	12,000 km
Color	White
First Registration	2025-07-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left rocker panel, Outer-side deformation. 2. Right rocker panel, Scratch damage. 3. Headliner, Soiling. 4. Headliner, Soiling.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.