


Vehicle Detail Report

Jetour X70 2023 1.5T DCT To surpass PRO 7 seat

Basic Information

Brand	Jetour
Mileage	18,500 km
Color	White
First Registration	2023-11-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Radiator support, Deformation. 2. Left bottom side member, Left rocker panel, Outer-side deformation. 3. Right bottom edge beam, Right rocker panel, Outer-side deformation. 4. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal. 5. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 6. Left front door, Scratch damage, Deformation. 7. Left headlight, Modified. 8. Right headlight, Modified. 9. Driver's seat, Driver's seat, Modified. 10. Passenger seat, Front passenger seat, Modified. 11. Rear seats, Damage, Modified. 12. Front subframe, Corrosion. 13. Front left shock absorber, Left front suspension, Corrosion. 14. Front right shock absorber, Right front suspension, Corrosion. 15. Rear left shock absorber, Left rear suspension, Corrosion. 16. Rear right shock absorber, Right rear suspension, Corrosion.

- "●" = Standard equipment
- "_" = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.