

Vehicle Detail Report

Geely Preface 2020 2.0T Luxury type

Basic Information

Brand	Geely
Mileage	50,000 km
Color	Black
First Registration	2021-07-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Radiator support, Signs of removal. 2. Left rocker panel, Scratch damage, Inner-side deformation. 3. Right rocker panel, Scratch damage. 4. Inner side of left C-pillar, Scratch. 5. Inner side of right C-pillar, Scratch. 6. Front passenger seat rails and frame, Corrosion. 7. Left sill wiring harness, Dust and sand residue. 8. Right front seat belt, Soiling. 9. Headliner, Soiling. 10. Left rear quarter panel, Scratch. 11. Right rear quarter panel, Scratch, Paint repair, Body panel repair. 12. Rear seats, Soiling. 13. Headliner, Soiling. 14. Right front seat belt, Soiling.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.