


Vehicle Detail Report

Honda Civic 2015 FK2 TYPE R European version

Basic Information

Brand	Honda
Mileage	51,000 km
Color	Blue
First Registration	2017-03-01
Transfer Count	5

Vehicle Images





Vehicle Condition

1. Left rear frame rail, Accessory deformation. 2. Left sill wiring harness, Dust and sand residue. 3. Airbag, Signs of removal.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.