

Vehicle Detail Report

Toyota Crown Kluger 2023 Intelligent electric hybrid double engine 2.5L E-CVT Four-wheel drive Premium Edition

Basic Information

Brand	Toyota
Mileage	44,000 km
Color	Black
First Registration	2023-11-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal. 2. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 3. Hood, Hood, Scratch damage. 4. Front bumper, Paint repair, Replaced, Scratch damage, Signs of removal. 5. Rear bumper, Scrape. 6. Left front door, Paint chip, Scratch damage. 7. Right front door, Paint chip, Scratch damage. 8. Left rear door, Scratch damage. 9. Right rear door, Paint chip, Scratch damage. 10. Trunk lid, Trunk lid, Scratch damage. 11. Left front fender, Scratch damage. 12. Right front fender, Scratch damage. 13. Left rear quarter panel, Scratch. 14. Right rear quarter panel, Scratch damage. 15. Windshield, Stone chip. 16. Left headlight, Signs of removal, Replaced. 17. Right tail light, Scratch.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.