

Vehicle Detail Report

Exeed Lingyun 2024 Lingyun 400T Two-Drive Star Edition

Basic Information

Brand	Exeed
Mileage	13,000 km
Color	Black
First Registration	2024-03-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Left upper side rail, Scratch. 2. Right upper side rail, Scratch. 3. Right rocker panel, Scratch damage. 4. Inner side of right B-pillar, Scratch. 5. Inner side of right C-pillar, Scratch. 6. Front bumper, Scrape, Scratch damage. 7. Rear bumper, Paint chip, Scrape. 8. Left front door, Paint chip, Scrape. 9. Right front door, Paint chip, Scratch. 10. Left rear door, Paint chip, Scratch. 11. Right rear door, Paint chip, Scratch. 12. Trunk lid, Scratch. 13. Left front fender, Scrape, Scratch. 14. Right front fender, Scratch. 15. Left rear quarter panel, Scratch. 16. Right rear quarter panel, Scratch. 17. Left tail light, Scratch. 18. Right tail light, Scratch.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.