



Vehicle Detail Report

Volkswagen Magotan 2020 380TSI DSG Luxury type

Basic Information

Brand	Volkswagen
Mileage	65,000 km
Color	Black
First Registration	2021-05-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Left upper side rail, Paint repair. 2. Driver's seat rails and frame, Signs of removal. 3. Front passenger seat rails and frame, Signs of removal. 4. Left rear quarter panel, Paint repair, Body panel repair. 5. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.