

Vehicle Detail Report

Changan Eado 2020 PLUS Blue whale NE 1.4T GDI Automatic Deluxe

Basic Information

Brand	Changan
Mileage	71,000 km
Color	Silver-gray
First Registration	2020-12-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right upper side rail, Paint repair. 2. Inner side of left B-pillar, Scratch, Dent. 3. Driver's seat rails and frame, Signs of removal. 4. Front passenger seat rails and frame, Signs of removal. 5. Left rear quarter panel, Paint repair, Body panel repair. 6. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.