

Vehicle Detail Report




Jetour Dasheng 2025 1.5T DCT Luxury

Basic Information

Brand	Jetour
Mileage	6,000 km
Color	Dark gray
First Registration	2024-11-01
Transfer Count	1

Vehicle Images







Vehicle Condition

1. Left bottom side member, Left rocker panel, Scratch damage. 2. Right, C, Column Sealing, Inner side of right C-pillar, Scratch. 3. Right rear quarter panel, Scratch.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.