

Vehicle Detail Report

Toyota Wildlander 2022 Dual Power 2.5L Two-wheel drive luxury PLUS version

Basic Information

Brand	Toyota
Mileage	80,500 km
Color	White
First Registration	2022-09-01
Transfer Count	1

Vehicle Images







Vehicle Condition

1. Left rocker panel, Scratch damage. 2. Inner side of right C-pillar, Scratch. 3. Driver's seat rails and frame, Signs of removal. 4. Front passenger seat rails and frame, Signs of removal. 5. Engine valve cover, Oil leakage. 6. Hood, Paint chip. 7. Front bumper, Paint repair, Scrape. 8. Right front wheel rim, Scrape. 9. Left rear wheel rim, Scrape. 10. Right rear wheel rim, Scrape. 11. Trunk lid, Paint repair, Replaced. 12. Right front fender, Paint repair. 13. Driver's seat, Wear. 14. Right rear suspension, Oil leak.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.