


Vehicle Detail Report

Mazda CX-5 2019 2.0L Automatic two-wheel drive smart type China V

Basic Information

Brand	Mazda
Mileage	50,000 km
Color	Blue
First Registration	2019-01-01
Transfer Count	1

Vehicle Images







Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Scratch. 2. Right, C, Column Sealing, Inner side of right C-pillar, Scratch, Deformation. 3. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal. 4. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 5. Left rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.